



Photo 15: View (looking north) of the north-central and northern portions of the T-108 shoreline; the bank in this area is armored with rip-rap.



Photo 16: View (looking south from the S Oregon St ROW end) of the northern portion of the T-108 shoreline. The Duwamish/Diagonal CSO/SD and EOF outfalls are nearby, and the location of the Duwamish Siphon is indicated by the sign.